

# Lead and Copper Tap Sample Analysis and Result Ranking

Reporting Format 62-550.730(4)(a)

System Name: Pluris South Gate

Date Submitted to Lab: 08/16/23

PWS-ID: 6588003

Analysis Date: 08/18/23

Laboratory Name: Benchmark EnviroAnalytical, Inc.

Lab Analysis method: SM3113B

Lab-ID: E84167

Lead or Copper (list one): Lead

Laboratory Contact Person: R. Sampson

Method Detection Limit: 0.00067 mg/L

Phone: (941) 723 - 9986

90th Percentile Value: 0.001 mg/L

| A | RANK | LOCATION CODE NO.     | TIER | LAB SAMPLE ID | DATE SITE SAMPLED | LEAD (mg/L) | COPPER (mg/L) |
|---|------|-----------------------|------|---------------|-------------------|-------------|---------------|
|   | 1    | 2404 Tulp St          |      | 23081011 001  | 08/15/23          | 0.00067 U   |               |
|   | 2    | 4540 Beneva Rd        |      | 23081011 004  | 08/15/23          | 0.00067 U   |               |
|   | 3    | 4517 Beneva Rd        |      | 23081011 005  | 08/15/23          | 0.00067 U   |               |
|   | 4    | 3427 Key Ave          |      | 23081011 006  | 08/15/23          | 0.00067 U   |               |
|   | 5    | 3212 Pine Valley Dr   |      | 23081011 007  | 08/15/23          | 0.00067 U   |               |
|   | 6    | 3504 Jaffa Dr         |      | 23081011 009  | 08/15/23          | 0.00067 U   |               |
|   | 7    | 2203 Brookhaven Dr    |      | 23081012 002  | 08/15/23          | 0.00067 U   |               |
|   | 8    | 3145 Bougainvillea St |      | 23081012 004  | 08/15/23          | 0.00067 U   |               |
|   | 9    | 2138 River Ridge Dr   |      | 23081012 005  | 08/15/23          | 0.00067 U   |               |
|   | 10   | 2706 Sheridan Dr      |      | 23081012 007  | 08/15/23          | 0.00067 U   |               |
|   | 11   | 2405 S Shade Ave      |      | 23081012 008  | 08/15/23          | 0.00067 U   |               |
|   | 12   | 1725 Riviera Cir      |      | 23081012 009  | 08/15/23          | 0.00067 U   |               |
|   | 13   | 3516 S Shade Ave      |      | 23081012 010  | 08/16/23          | 0.00067 U   |               |
|   | 14   | 2440 Tulp St          |      | 23081013 001  | 08/16/23          | 0.00067 U   |               |
|   | 15   | 3711 Thornton Pl      |      | 23081013 002  | 08/16/23          | 0.00067 U   |               |
|   | 16   | 3058 Hyde Park St     |      | 23081013 003  | 08/16/23          | 0.00067 U   |               |
|   | 17   | 2864 Homasassa Rd     |      | 23081013 004  | 08/16/23          | 0.00067 U   |               |
|   | 18   | 2838 Bougainvillea St |      | 23081013 005  | 08/16/23          | 0.00067 U   |               |
|   | 19   | 3041 Homasassa Rd     |      | 23081013 008  | 08/16/23          | 0.00067 U   |               |
|   | 20   | 2491 S Lockwood Ridge |      | 23081013 009  | 08/16/23          | 0.00067 U   |               |

CERTIFICATION. The tap samples used for lead and copper analyses were submitted by the above PWS. Each sample container had one liter of solution ( $\pm 100\text{mL}$ ). All samples were taken properly by the above system and analyzed in accordance with the requirements in subsection 62-550.550(1), F.A.C. The sampling dates were reported for each sample received. I hereby certify that all data submitted are correct.

SIGNATURE OF AUTHORIZED LABORATORY REPRESENTATIVE: Haley Rin

NAME (Please Print): Kathleen Gauthier/Haley Richardson

TITLE and DATE: QC Officer/QA Officers 09/20/23

# Lead and Copper Tap Sample Analysis and Result Ranking

Reporting Format 62-550.730(4)(a)

System Name: Pluris South Gate

Date Submitted to Lab: 08/16/23

PWS-ID: 6588003

Analysis Date: 08/18/23

Laboratory Name: Benchmark EnviroAnalytical, Inc.

Lab Analysis method: SM3113B

Lab-ID: E84167

Lead or Copper (list one): Lead

Laboratory Contact Person: R. Sampson

Method Detection Limit: 0.00067 mg/L

Phone: (941) 723 - 9986

90th Percentile Value: 0.001 mg/L

| A | RANK | LOCATION CODE NO.     | TIER | LAB SAMPLE ID | DATE SITE SAMPLED | LEAD (mg/L.) | COPPER (mg/L) |
|---|------|-----------------------|------|---------------|-------------------|--------------|---------------|
|   | 21   | 3115 Bougainvillea St |      | 23081013 010  | 08/16/23          | 0.00067 U    |               |
|   | 22   | 2350 Tulip St         |      | 23081011 003  | 08/15/23          | 0.0010 I     |               |
|   | 23   | 3125 Meyer Dr         |      | 23081011 008  | 08/15/23          | 0.0010 I     |               |
|   | 24   | 3517 S Shade Ave      |      | 23081011 010  | 08/15/23          | 0.0010 I     |               |
|   | 25   | 2410 Tulip St         |      | 23081012 001  | 08/15/23          | 0.0010 I     |               |
|   | 26   | 3201 Village Green Dr |      | 23081012 003  | 08/15/23          | 0.0010 I     |               |
|   | 27   | 3231 Rose St          |      | 23081012 006  | 08/15/23          | 0.0010 I     |               |
|   | 28   | 3623 Tuttle Ave       |      | 23081013 006  | 08/16/23          | 0.0010 I     |               |
|   | 29   | 2519 Tulip St         |      | 23081011 002  | 08/15/23          | 0.0020 I     |               |
|   | 30   | 3506 Mineola Dr       |      | 23081013 007  | 08/16/23          | 0.0020 I     |               |
|   | 31   |                       |      |               |                   |              |               |
|   | 32   |                       |      |               |                   |              |               |
|   | 33   |                       |      |               |                   |              |               |
|   | 34   |                       |      |               |                   |              |               |
|   | 35   |                       |      |               |                   |              |               |
|   | 36   |                       |      |               |                   |              |               |
|   | 37   |                       |      |               |                   |              |               |
|   | 38   |                       |      |               |                   |              |               |
|   | 39   |                       |      |               |                   |              |               |
|   | 40   |                       |      |               |                   |              |               |

CERTIFICATION. The tap samples used for lead and copper analyses were submitted by the above PWS. Each sample container had one liter of solution ( $\pm 100$ mL). All samples were taken properly by the above system and analyzed in accordance with the requirements in subsection 62-550.550(1), F.A.C. The sampling dates were reported for each sample received. I hereby certify that all data submitted are correct.

SIGNATURE OF AUTHORIZED LABORATORY REPRESENTATIVE: Haley Rin

NAME (Please Print): Kathleen Gauthier/Haley Richardson

TITLE and DATE: QC Officer/QA Officers 09/20/23

# Lead and Copper Tap Sample Analysis and Result Ranking

Reporting Format 62-550.730(4)(a)

System Name: Pluris South Gate

Date Submitted to Lab: 08/16/23

PWS-ID: 6588003

Analysis Date: 08/21/23

Laboratory Name: Benchmark EnviroAnalytical, Inc.

Lab Analysis method: 200.7

Lab-ID: E84167

Lead or Copper (list one): Copper

Laboratory Contact Person: R. Sampson

Method Detection Limit: 0.004 mg/L

Phone: (941) 723 - 9986

90th Percentile Value: 0.0980 mg/L

| A | RANK | LOCATION CODE NO.        | TIER | LAB SAMPLE ID | DATE SITE SAMPLED | LEAD (mg/L) | COPPER (mg/L) |
|---|------|--------------------------|------|---------------|-------------------|-------------|---------------|
|   | 1    | 3041 Homasassa Rd        |      | 23081013 008  | 08/16/23          |             | 0.0040 I      |
|   | 2    | 3506 Mineola Dr          |      | 23081013 007  | 08/16/23          |             | 0.0050 I      |
|   | 3    | 3516 S Shade Ave         |      | 23081012 010  | 08/16/23          |             | 0.0070 I      |
|   | 4    | 2440 Tulip St            |      | 23081013 001  | 08/16/23          |             | 0.0080 I      |
|   | 5    | 2491 S Lockwood Ridge Rd |      | 23081013 009  | 08/16/23          |             | 0.0090 I      |
|   | 6    | 3212 Pine Valley Dr      |      | 23081011 007  | 08/15/23          |             | 0.0130 I      |
|   | 7    | 4540 Beneva Rd           |      | 23081011 004  | 08/15/23          |             | 0.0150 I      |
|   | 8    | 3125 Meyer Dr            |      | 23081011 008  | 08/15/23          |             | 0.0160        |
|   | 9    | 2410 Tulip St            |      | 23081012 001  | 08/15/23          |             | 0.0180        |
|   | 10   | 2706 Sheridan Dr         |      | 23081012 007  | 08/15/23          |             | 0.0180        |
|   | 11   | 2405 S Shade Ave         |      | 23081012 008  | 08/15/23          |             | 0.0200        |
|   | 12   | 3623 Tuttle Ave          |      | 23081013 006  | 08/16/23          |             | 0.0210        |
|   | 13   | 3201 Village Green Dr    |      | 23081012 003  | 08/15/23          |             | 0.0230        |
|   | 14   | 2404 Tulip St            |      | 23081011 001  | 08/15/23          |             | 0.0290        |
|   | 15   | 2864 Homasassa Rd        |      | 23081013 004  | 08/16/23          |             | 0.0300        |
|   | 16   | 4517 Beneva Rd           |      | 23081011 005  | 08/15/23          |             | 0.0310        |
|   | 17   | 2138 River Ridge Dr      |      | 23081012 005  | 08/15/23          |             | 0.0310        |
|   | 18   | 2350 Tulip St            |      | 23081011 003  | 08/15/23          |             | 0.0340        |
|   | 19   | 1725 Riviera Cir         |      | 23081012 009  | 08/15/23          |             | 0.0410        |
|   | 20   | 2203 Brookhaven Dr       |      | 23081012 002  | 08/15/23          |             | 0.0460        |

CERTIFICATION. The tap samples used for lead and copper analyses were submitted by the above PWS. Each sample container had one liter of solution ( $\pm 100\text{mL}$ ). All samples were taken properly by the above system and analyzed in accordance with the requirements in subsection 62-550.550(1), F.A.C. The sampling dates were reported for each sample received. I hereby certify that all data submitted are correct.

SIGNATURE OF AUTHORIZED LABORATORY REPRESENTATIVE: Haley Rin

NAME (Please Print): Kathleen Gauthier/Haley Richardson

TITLE and DATE: QC Officer/QA Officers 09/20/23

# Lead and Copper Tap Sample Analysis and Result Ranking

Reporting Format 62-550.730(4)(a)

System Name: Pluris South Gate

Date Submitted to Lab: 08/16/23

PWS-ID: 6588003

Analysis Date: 08/21/23

Laboratory Name: Benchmark EnviroAnalytical, Inc.

Lab Analysis method: 200.7

Lab-ID: E84167

Lead or Copper (list one): Copper

Laboratory Contact Person: R. Sampson

Method Detection Limit: 0.004 mg/L

Phone: (941) 723 - 9986

90th Percentile Value: 0.0980 mg/L

| A | RANK | LOCATION CODE NO.     | TIER | LAB SAMPLE ID | DATE SITE SAMPLED | LEAD (mg/l.) | COPPER (mg/l.) |
|---|------|-----------------------|------|---------------|-------------------|--------------|----------------|
|   | 21   | 3517 S Shade Ave      |      | 23081011 010  | 08/15/23          |              | 0.0580         |
|   | 22   | 3145 Bougainvillea St |      | 23081012 004  | 08/15/23          |              | 0.0580         |
|   | 23   | 3427 Key Ave          |      | 23081011 006  | 08/15/23          |              | 0.0620         |
|   | 24   | 3115 Bougainvillea St |      | 23081013 010  | 08/16/23          |              | 0.0790         |
|   | 25   | 3504 Jaffa Dr         |      | 23081011 009  | 08/15/23          |              | 0.0930         |
|   | 26   | 2838 Bougainvillea St |      | 23081013 005  | 08/16/23          |              | 0.0950         |
|   | 27   | 3231 Rose St          |      | 23081012 006  | 08/15/23          |              | 0.0980         |
|   | 28   | 3711 Thornton Pl      |      | 23081013 002  | 08/16/23          |              | 0.1050         |
|   | 29   | 3058 Hyde Park St     |      | 23081013 003  | 08/16/23          |              | 0.1080         |
|   | 30   | 2519 Tulip St         |      | 23081011 002  | 08/15/23          |              | 0.1880         |
|   | 31   |                       |      |               |                   |              |                |
|   | 32   |                       |      |               |                   |              |                |
|   | 33   |                       |      |               |                   |              |                |
|   | 34   |                       |      |               |                   |              |                |
|   | 35   |                       |      |               |                   |              |                |
|   | 36   |                       |      |               |                   |              |                |
|   | 37   |                       |      |               |                   |              |                |
|   | 38   |                       |      |               |                   |              |                |
|   | 39   |                       |      |               |                   |              |                |
|   | 40   |                       |      |               |                   |              |                |

CERTIFICATION. The tap samples used for lead and copper analyses were submitted by the above PWS. Each sample container had one liter of solution ( $\pm 100$  mL). All samples were taken properly by the above system and analyzed in accordance with the requirements in subsection 62-550.550(1), F.A.C. The sampling dates were reported for each sample received. I hereby certify that all data submitted are correct.

SIGNATURE OF AUTHORIZED LABORATORY REPRESENTATIVE: Haley Rin

NAME (Please Print): Kathleen Gauthier/Haley Richardson

TITLE and DATE: QC Officer/QA Officers 09/20/23